

## Aviation Programs

## AIRPORT HISTORICAL CIP REPORT

## MC RAE - TELFAIR-WHEELER - MQW

Fiscal Year	CIP Historical Description	Federal Cost	State Cost	Local Cost	Total Cost
1980	Mark Rwy and Twy (Statewide Project)	\$0.00	\$3,268.00	\$0.00	\$3,268.00
	<b>Annual Total:</b>	<b>\$0.00</b>	<b>\$3,268.00</b>	<b>\$0.00</b>	<b>\$3,268.00</b>
1982	Lighting Repair and Relocate Wind Cone.	\$0.00	\$4,200.00	\$1,312.00	\$5,512.00
	<b>Annual Total:</b>	<b>\$0.00</b>	<b>\$4,200.00</b>	<b>\$1,312.00</b>	<b>\$5,512.00</b>
1985	Rotating Beacon - Rehabilitation. Radio Control.	\$0.00	\$4,461.00	\$1,487.02	\$5,948.02
	<b>Annual Total:</b>	<b>\$0.00</b>	<b>\$4,461.00</b>	<b>\$1,487.02</b>	<b>\$5,948.02</b>
1992	Crack Seal Rwy, Twy, and Apron	\$0.00	\$11,305.00	\$3,768.00	\$15,073.00
	<b>Annual Total:</b>	<b>\$0.00</b>	<b>\$11,305.00</b>	<b>\$3,768.00</b>	<b>\$15,073.00</b>
1997	Resurface Runway, Taxiway, & Apron	\$0.00	\$170,093.00	\$55,544.00	\$225,637.00
	Runway Lights (MIRL)	\$0.00	\$73,722.00	\$24,574.00	\$98,296.00
	<b>Annual Total:</b>	<b>\$0.00</b>	<b>\$243,815.00</b>	<b>\$80,118.00</b>	<b>\$323,933.00</b>
2000	ALP Update and Environmental Assessment for Runway Extension	\$0.00	\$48,750.00	\$16,250.00	\$65,000.00
	<b>Annual Total:</b>	<b>\$0.00</b>	<b>\$48,750.00</b>	<b>\$16,250.00</b>	<b>\$65,000.00</b>
2003	Improve Runway Safety Area	\$150,000.00	\$0.00	\$16,667.00	\$166,667.00
	<b>Annual Total:</b>	<b>\$150,000.00</b>	<b>\$0.00</b>	<b>\$16,667.00</b>	<b>\$166,667.00</b>
	<b>Grand Total:</b>	<b>\$150,000.00</b>	<b>\$315,799.00</b>	<b>\$119,602.02</b>	<b>\$585,401.02</b>